

















EN1176








**260329**  
**4203**  
**422213**  
**423213**  
**424213**  
**448000**  
**42008010**  
**42077010**  
**42277010**  
**42477010**  
**MA42099**  
**MA426121**  
**MASW39775**  
**MASW42193**


**42008010**



**Above Ground**

**OM**



8105808



**Sunken Foundation**

**S**


8105812



**Cast In Place**

**CC**


8105802




**Loosefill**

**BM**

8077980






👁 **MA426121**  
1,00 x 1,00m

👁 **4203**  
1,00 x 0,67m

👁 **MA42099**  
x2

+1,50m

👁 **MASW42193**



👁 **MASW39775**  
x4

👁 **423213 [S]**  
👁 **422213 [OM]**  
👁 **424213 [BM]**

👁 **42077010 [S]**  
👁 **42277010 [OM]**  
👁 **42477010 [BM]**

